

It's recommended to use a soft cloth or gloves when handling the fixture.

Assembly Instructions

1. Attach universal crossbar to Junction box, aligning holes to desired location in regard to canopy ball screws
2. Connect positive supply wire (typically black or the smooth, unmarked side of the two-conductor cord) to positive fixture lead with appropriately sized twist on connector.
3. Connect negative supply wire (typically white or the ribbed, marked side of the two-conductor cord) to negative fixture lead.
4. Please refer to the grounding instructions to complete all electrical connections.
5. Tuck the connected wires into the junction box and raise the canopy and rod holding the chandelier. Align screw holes from canopy to the universal crossbar. Thread the ball screws through, tightening the canopy flush to the ceiling.

Grounding Instructions

For positive grounding in a 3-wire electrical system, fasten the fixture ground wire (typically copper or green plastic coated) to the fixture mounting crossbar with the ground screw.

Note: On straps for screw support fixtures, first install the two mounting screws in strap. Any remaining tapped hole may be used for the ground screw.

Light Bulb Replacement

Loosen screw tightener to release globe holder cap whilst holding the glass globe. Slide neckless globe cover up the rod. Shift glass globe upward to release from globe holder. Replace bulb and place globe shade back on globe holder. Slide cap down over globe opening, and tighten screw to secure in place.

